YAKIMA VALLEY COLLEGE

Stormwater Program

Yakima valley College

Annual Report

- Department of Ecology
- BPM Best management Practice
- Public Education
- Secondary Permit
 - Responsible for Campus
 - Notification D.O.E. City of Yakima

Washington Department of Ecology Submission Cover Letter

WQWebSubmittal - Submittal Submission Id: 1533527 - 3/28/2016 1:42:57 PM

Report Received Dated:

3/28/2016 1:42:58 PM

Company Name	Signer Name	System Name
Yakima Valley Community College	Casey Rice	WQWebPortal

Attachments:

Document Name of Description	Document File Name
Submitted Copy of Record for Yakima Valley Community College	Copy of Record YakimaValleyCommunityCollege Monday March 28 2016

Annual Report - Department of Ecology

Stormwater Program

Stormwater Inventory

- ▶ 38 Catch Basins with Infiltration
- 28 Catch Basins to City Stormwater System
- ► 7 Drywells with Infiltration
- ► 7 Swales with Infiltration
- 81 Roof Drains Connected to City Stormwater System



Catch Basin - Parking Lot "I"




Remember Only Rain Down The Drain



Swale in Parking Lot "P"



Swale - Grandview Campus



Permeable - Pavement



Permeable - Pavement



Drywell - Parking Lot Central Receiving

BPM - Spill Kit

- Gloves
- Goggles
- Cones
- Absorbent Pads



Contact Department of Ecology

BPM

Dandy Sacks

Mesh Filters



Best Management Practice



Central Washington Fair Booth - 2016

Questions?

Facility Operations 574 - 4696 Report Illicit Discharge 574 - 4692

